### **DEPARTMENT OF TRANSPORTATION**


DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453

(707) 649-5493

Contractor:



**Location:** Job Site

Yes

No

N/A

Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 1.28

### WELDING INSPECTION REPORT

Resident Engineer: Siegenthaler, Peter **Report No:** WIR-018134 **Date Inspected:** 10-Nov-2010

Address: 333 Burma Road City: Oakland, CA 94607

American Bridge/Fluor Enterprises, a JV

**OSM Arrival Time:** 730 **Project Name:** SAS Superstructure **OSM Departure Time:** 1600 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

**CWI Name:** William Norris **CWI Present:** Yes No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes No N/A **Approved Drawings:** Yes No **Approved WPS:** 

**Delayed / Cancelled:** 

34-0006 **Bridge No: Component:** S.A.S. components

### **Summary of Items Observed:**


The Quality Assurance Inspector (QAI), Scott Croff, was present at the Self Anchored Span (SAS) job site to observe the scheduled fabrication and welding of components for the SFOBB project.

The QAI reviewed contract related documents including the submitted and approved Welding Quality Control Plan (WQCP) and approved revisions to the WQCP. The QAI completed the formal review of the contractor's submittal #1536 Rev.31. See the appropriate TL-20 report for additional information. The QAI continued reviewing submittal rev.32, the 4 informal weld report packages and consolidating the information from welding report submittals to identify missing reports of inspections. The QAI continued generating a weld specific tracking list from the contractor's welding reports.

The QAI accompanied Caltrans personnel Jason Wilcox, Philip He, ABF representative Chuck Kanapicki and Quality Control (QC) Inspector William Norris in conducting the post arrival inspection of voyage 5 OBG components. During the inspection of OBG 9W, the QAI noted that painted surfaces have been marred from general shipping and handling. The QAI noted that a welded attachment has not been properly removed from the deck of the OBG. There was no other shipping related damage observed during this inspection. See the attached photos.

# WELDING INSPECTION REPORT

(Continued Page 2 of 2)





## **Summary of Conversations:**

The QAI had general conversations with ABF and Caltrans personnel during this shift. As noted above, there were general conversations about the appearances of the components examined for the post arrival inspection. The QAI relayed the observations of post arrival inspection and the status of document reviews to the QAI Lead Bill Levell. Except as described above, there were no other notable conversations or observations.

### **Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Mohammad Fatemi, (916) 813-3677, who represents the Office of Structural Materials for your project.

Inspected By:	Croff,Scott	Quality Assurance Inspector
Reviewed By:	Levell,Bill	QA Reviewer